

Agenda Item 10.2 - Action from ROSPA report

Junior/toddler playground

1. Fencing and gates in need of repair - This has been completed
2. Caps on item need replacing
3. Rocker elephant – Needs cleaning
4. Rocker seesaw- surface cracking in need of repair
The springs need to be repainted

Senior Playground

1. Fencing and gates in need of repair - This has been completed
2. Agility trim trial – In need of replacing as decaying and lots of work required
3. Multiplay – corrosion in need of replacing
4. Rocker platform – trip hazard in surface
5. Combination goal – corroding and dangerous – need to remove net to avoid climbing and potential accidents

The Green

1. Make sure trees are inspected regularly
2. Consider levelling the bus stop path
3. Include no kite flying in signage

This are points suggested/recommended by ROSPA which needs to be discussed if any action should be taken before the replacement of the playgrounds.